THE CONDITION OF THE EXISTING BUILDING IS TO BE CHECKED PRIOR TO THE COMMENCEMENT OF ANY WORKS TO DETERMINE IF ADDITIONAL REMEDIAL WORKS ARE REQUIRED - ALL FINDINGS ARE TO BE REPORTED BACK TO ST ARCHITECTURE AND DESIGN. Existing roof structure to be checked for stability and defects Water recylling 0 (not supplied) - 50mm Celotex GA4000 insulation between rafters 70mm Celotex GA4000 insulation below rafters - 25mm x 50mm timber battens - 12.5mm plasterboard with plaster skim finish DETAIL OF RAFTER TRIMMING IS TO BE DETERMINED ONCE THE CONDITION OF THE ROOF HAS BEEN ASSESSED BEDROOM \_ 12.5mm plasterboard with plaster skim Vapour barrier - 50mm Celotex GA4000 insulation 25mm x 50mm timber battens 12.5mm plasterboard with plaster skim — Vapour barrier -50mm Celotex GA4000 insulation -25mm x 50mm timber battens -└ 75mm finishing screed and floor finish — Mın 75mm Celotex GA4000 — I 00mm thick concrete slab LOUNGE LOUNGE Existing floor level to be reduced by at least 60mm - dependant of wall and foundation structure FFL = 0 - 75mm finishing screed and floor finish Min 75mm Celotex GA4000 100mm thick concrete slab 1200g damp proof membrane - 50mm sand blinding - 150mm consolidated hardcore Existing floor to be excavated to a level surface to allow for new floor to be installed TRIAL HOLES ESTABLISHED UNDERPINNING IS REQUIRED - DETAILS AS PER STRUCTURAL Section A-A **ENGINEERS DESIGN** 

& DESIGN

53 Howitt Street, Heanor, Derbyshire, DE75 7AU. Tel 07973 520281

Drawing

Drawn by ST	Γ	Date:	
Designed by ST	Г	Date:	
Checked by		Date:	
Approved by		Date:	
Drawing No.			Revision
			А

Rev By Chk App Date Description

Email info@starchitecture.co.uk Web www.starchitecture.co.uk

Section A-A

Drawing Scale: 1:20 DO NOT SCALE FROM DRAWING

Frame 04-15

© Crown copyright and database rights 2015 Ordnance Survey 100030649